




How To Reshape Cage Veiling or Netting on a Fascinator or Hat



So, you got a great hat or fascinator, but during storage or transit, the veiling got creased, flattened, or misshapen. Rejoice! There is something you can do to reshape the veiling! You will need a heat tool and a friend.

Tools:

heat gun or hair dryer

Steps

1	Determine how you want the veiling to look and lay. (This photo shows the veil before we reshaped it.)	
2	Have a friend hold the veil in a manner that approximates the desired shape of the veiling.	
3	Turn on the heat tool or hair dryer and let it warm up.	

4	<p>Carefully avoiding your friend's fingers, direct the heat from the tool or dryer toward the veiling or mesh. Keep the heat tool between 4 and 6 inches from the veiling. The heat will reshape the veiling by melting it a little bit, so don't concentrate it on one part of the veiling for too long.</p>	
5	<p>When you have achieved the proper shape, turn off the heat tool and let it cool. (This photo shows the veil after we reshaped it.)</p>	

Now, wear that gorgeous hat or fascinator!